



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:	
Company	Gary E. Gray Resident Agent
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070041
Inspection Type:	COMPLETE
Inspection Date:	Friday, February 11, 2005
Start Date/Time:	2/11/2005 10:00:00 AM
End Date/Time:	2/11/2005 2:00:00 PM
Last Inspection:	Wednesday, January 12, 2005

Inspector: Steve Demczak, Environmental Scientist III

Weather: Partly Cloudy, Snow Covered

InspectionID Report Number: 547

Accepted by: pgrubaug
 3/3/2005

Permittee: **WEST RIDGE RESOURCES**
 Operator: **WEST RIDGE RESOURCES**
 Site: **WEST RIDGE MINE**
 Address: **PO BOX 1077, PRICE UT 84501**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

4,382.55	Total Permitted
29.06	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending Division Order: Division Order DO00A-7, Extension granted until May 2004. The Division received a response to Division Order DO-00A-7 on June 3, 2004. The Division Order was sent back to the permittee with deficiencies. The Division met with the permittee on November 29, 2004 and discussed the deficiencies. The Division expects a response by March 10, 2005.

Inspector's Signature

Date Tuesday, March 01, 2005

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
 Where ideas connect™

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit is effective 04/01/2002 and expires 04/01/2009. Other documents include the following:

- Certificate of Insurance issued 07/01/2004 and terminates 07/01/2005.
- Reclamation agreement is dated April 1999 and signed by both parties.
- UPDES permit UTG040013 effective 05/01/2003 and expires midnight 04/30/2008.
- Air Quality permit DAQE-055-99, issued 01/14/1999.
- SPCC Plan dated 09/20/2004.

2. Signs and Markers

The mine ID signs are located at the pump house and the entrance to the mine site from the county road. The signs contain the permit number, address, and phone number of the operator. Other signs and markers observed during the inspection meet the coal rules.

3. Topsoil

The topsoil pile was snow covered.

4.a Hydrologic Balance: Diversions

The diversions were open and water was flowing to the sediment pond.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond was inspected and no hazardous conditions were noticed during the inspection. The permittee conducted a fourth quarter sediment pond inspection on December 21, 2004. No hazardous conditions were reported.

4.c Hydrologic Balance: Other Sediment Control Measures

The roadside silt fences will need cleaning out by spring. Sediment has started to build-up behind the fences.

4.d Hydrologic Balance: Water Monitoring

The permittee is in the process of taking water monitoring for the first quarter.

4.e Hydrologic Balance: Effluent Limitations

The permittee was in compliance with the UPDES permit for the 4th quarter of 2004. There are two point source discharge points at West Ridge. Point 001 is the sediment pond and 002 is the mine discharge.

8. Noncoal Waste

The property was generally clear of non-coal waste material.

14. Subsidence Control

Information on subsidence is in the annual report.

18. Support Facilities, Utility Installations

No new support facilities have been added since the last inspection.

20. Air Quality Permit

The air quality permit DAQE-055-99 referenced above remains in effect.

21. Bonding and Insurance

The insurance referenced in item #1 above is through Federal Insurance Co., policy #3710-95-30. The insurance has explosion coverage, met the minimum requirements, listed the Division as the certificate holder, and has the proper language on the notification policy.

Bond No. 21-60-38, issued 03/19/1999 is for \$2,117,000 from National Union Fire Insurance Company.

22. Other

The SPCC Plan has been re-evaluated and appropriate changes made. The SPCC plan has been re-certified by a Registered P.E. on September 20, 2004.