

**From:** "Michael Hansen" <Mhansen@rbgengineering.com>  
**To:** <dshaver@andalex.com>, <jlewis@andalex.com>, <jsorensen@andalex.com>, <James\_Kohler@blm.gov>, <Jeff\_McKenzie@blm.gov>, <Stan\_Perkes@blm.gov>, <Steve\_Falk@blm.gov>, <steve\_rigby@blm.gov>, <ecc@emerytelcom.net>, <mkstilson@hotmail.com>, "Brad Price" <bprice@rbgengineering.com>, "Rob Johnson" <robj@rbgengineering.com>, <bretdixon@utah.gov>, <davemarble@utah.gov>, <karlhouskeeper@utah.gov>, <pamgrubaughlittig@utah.gov>, <petehess@utah.gov>, <waynehedberg@utah.gov>  
**Date:** 3/20/2006 8:00:28 PM  
**Subject:** Grassy Trail seismic Graph Correction

due to scale errors on the first copy of this graph I am sending a corrected version. This chart shows all of the earthquakes documented by the UUSS along with the PGA values recorded by us (between Jan to March 16, 2006). It also show how activity has picked up recently. Sorry for the mix up.

Michael Hansen  
Engineering Geologist

RB&G ENGINEERING Inc.  
1435 West 820 North  
Provo Ut. 84601

Ph 801-374-5771  
SLC 801-521-5771  
Fax 801-374-5773

email mhansen@rbgengineering.com

