

Incoming  
0070041

0079

**From:** "Michael Hansen" <Mhansen@rbgengineering.com>  
**To:** <James\_Kohler@blm.gov>, <Jeff\_McKenzie@blm.gov>, <Stan\_Perkes@blm.gov>, <Steve\_Falk@blm.gov>, <steve\_rigby@blm.gov>, <jllewelyn@co.carbon.ut.us>, <ecc@emerytelcom.net>, <sunny1@emerytelcom.net>, "Brad Price" <bprice@rbgengineering.com>, "Rob Johnson" <robj@rbgengineering.com>, <bretDixon@utah.gov>, <davemarble@utah.gov>, <karlhouskeeper@utah.gov>, <marcstilson@utah.gov>, <pamgrubaughlittig@utah.gov>, <petehess@utah.gov>, <waynehedberg@utah.gov>, <dshaver@utahamerican.com>  
**Date:** 8/28/2006 9:40:04 AM  
**Subject:** Grassy Trail Dam monitoring 8/25/06 seepage readings and site photos

Hi

At the request of Dave Shaver for Westridge Mine, RB&G Engineering has been asked to complete weekly site visits to make a visual inspection of the dam and surrounding landslides for signs of movement, take seepage readings, and photograph the existing site conditions.

It should be noted that the site visit on Friday 8/25/06 was during a heavy rain and hail storm. A lot of muddy water was ponding up in the low area at the toe of the dam. This water seeps into the toe drain, creating a muddy flow out of Seep #1 toe drain.

No cracks or signs of movement were noted at the dam.

Michael Hansen  
Engineering Geologist

RB&G ENGINEERING Inc.  
1435 West 820 North  
Provo Ut. 84601

Ph 801-374-5771  
SLC 801-521-5771  
Fax 801-374-5773

email mhansen@rbgengineering.com



Looking West



08/25/2006

Looking West



08/25/2006

Looking West



08/25/2006

Looking East



08/25/2006

Looking East



08/25/2006

Looking East



08/25/2006



West Abutment

08/25/2006



Downstream Face

08/25/2006

East Abutment



08/25/2006