

*Outgoing*

	<b>Citation for Non-Compliance</b>	<b>Citation #:</b> 10025
	<b>Utah Coal Regulatory Program</b>	<b>Permit Number:</b> C0070041
	1594 West North Temple, Salt Lake City, UT 84114 Phone: (801) 538-5340 Fax: (801) 359-3940	<b>Date Issued:</b> 07/31/2008
<input checked="" type="checkbox"/> <b>NOTICE OF VIOLATION</b>	<input type="checkbox"/> <b>CESSATION ORDER (CO)</b>	<input type="checkbox"/> <b>FAILURE TO ABATE CO</b>
<b>Permittee Name:</b> West Ridge Resources	<b>Inspector Number and ID:</b> 46 PHESS	
<b>Mine Name:</b> West Ridge Mine	<b>Date and Time of Inspection:</b> 06/30/2008 10:27 am	
<b>Certified Return Receipt Number:</b> Hand delivered	<b>Date and Time of Service:</b> 07/01/2008 8:00 am	
<b>Nature of condition, practice, or violation:</b>		
1) Failure to remove vegetative cover from disturbed area prior to mining activity (upper edge / west side of left fork coal storage area). 2) Failure to remove and segregate topsoil as a separate layer from the area to be disturbed (upper edge / west side of left fork coal storage area).		
<b>Provisions of Act, regulations, or permit violated:</b>		
1) R645-301-232.600 Timing and Vegetation Removal 2) R645-301- 232.100 Topsoil Removal / Segregation 3) R645-301-232.200 Insufficient Quantity or Poor Quality Topsoil / Segregation		
<input type="checkbox"/> <b>This order requires Cessation of ALL mining activities. (Check box if appropriate.)</b>		
<input type="checkbox"/> Condition, practice, or violation is creating an imminent danger to health or safety of the public.	<input type="checkbox"/> Permittee is/has been conducting mining activities without a Permit.	
<input type="checkbox"/> Condition, practice, or violation is causing or can reasonably be expected to cause significant, imminent environmental harm to land, air, or water resources.	<input type="checkbox"/> Permittee has failed to abate Violation(s) included in <input type="checkbox"/> Notice of Violation or <input type="checkbox"/> Cessation Order within time for abatement originally fixed or subsequently extended.	
<input checked="" type="checkbox"/> <b>This order requires Cessation of PORTION(S) of mining activities.</b>		
<b>Mining activities to be ceased immediately:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<b>Abatement Times (if applicable).</b>
All coal pushing activity in the left hand fork coal storage area will be stopped below the vegetation line where vegetation and topsoil have not been recovered.		Immediately
Removal of Coal from vegetated area by...		August 15, 2008 @ 17:00 Hours (30 days)
<b>Action(s) required:</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
1) Remove all coal from the vegetation above the cut bank / topsoil interface on the west side of the coal storage pit (the area starts west of the run-of-mine belt discharge and runs north for approximately 150 feet on the west side of the pit). 2) The Permittee must install "STOP" signs or other signs accepted by the Division to delimitate the top of the west cut bank / topsoil interface as the maximum height limit for the coal storage pile.		
<b>Mr. Dave Shaver, Resident Agent</b>	<b>PETE HESS</b>	
(Print) Permittee Representative	(Print) DOGM Representative	
<i>E-mailed to Permittee on 7/31/2008 Hard Copy via USPS</i>	<i>Pete Hess July 31, 2008 10:30 AM</i>	
Permittee Representative's Signature - Date	DOGM Representative's Signature - Date	
<b>SEE REVERSE SIDE Of This Form For Instructions And Additional Information</b>		