

0005

**From:** Karl Houskeeper  
**To:** rnetz@emerytelcom.net  
**CC:** Angela Nance; Daron Haddock; Suzanne Steab  
**Date:** 4/6/2009 2:33 PM  
**Subject:** March 2009 Inspection Reports  
**Attachments:** SPWF March 2009.pdf; SCA March 2009.pdf

*Manning*  
C0070048  
C0070035  
K

Rusty,

Attached are the March 2009 inspection reports for SPWF and SCA.

Thanks,  
Karl



State of Utah

Department of Natural Resources

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA  
Division Director

JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

Representatives Present During the Inspection:	
Company	Rusty Netz Environmental Coordinator
OGM	Karl Houskeeper Environmental Scientist III

# Inspection Report

Permit Number:	C0070042
Inspection Type:	PARTIAL
Inspection Date:	Thursday, March 19, 2009
Start Date/Time:	3/19/2009 8:00:00 AM
End Date/Time:	3/19/2009 10:00:00 AM
Last Inspection:	Tuesday, February 17, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 51 Deg. F.

InspectionID Report Number: 1950

Accepted by: jhelfric  
3/24/2009

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**  
 Operator: **SUNNYSIDE COGENERATION ASSOCIATES**  
 Site: **STAR POINT REFUSE**  
 Address: **ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

**Current Acreages**

152.81	<b>Total Permitted</b>
88.78	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

**Mineral Ownership**

- Federal
- State
- County
- Fee
- Other

**Types of Operations**

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: \_\_\_\_\_

Date Thursday, March 19, 2009

Karl Houskeeper, Environmental Scientist III  
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070042  
Inspection Type: PARTIAL  
Inspection Date: Thursday, March 19, 2009

**Inspection Continuation Sheet**

*Page 3 of 3*

**2. Signs and Markers**

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile appeared stable. No visible hazards were observed.



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Company, Name/Title. Rows include Rusty Netz Environmental Coordinator and OGM Karl Houskeeper Environmental Scientist III.

Inspection Report

Table with 2 columns: Field, Value. Fields include Permit Number, Inspection Type, Inspection Date, Start Date/Time, End Date/Time, Last Inspection.

Inspector: Karl Houskeeper, Environmental Scientist III
Weather: Clear, Temp. 56 Deg. F.
InspectionID Report Number: 1951

Accepted by: jhelfric
3/24/2009

Permittee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES
Site: SUNNYSIDE REFUSE & SLURRY
Address: ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539
County: CARBON
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Rows include Total Permitted (310.00), Total Disturbed (202.00), and Phases I, II, III.

Mineral Ownership

- Checkboxes for Federal, State, County, Fee (checked), Other.

Types of Operations

- Checkboxes for Underground, Surface, Loadout, Processing, Reprocessing (checked).

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Inspector's Signature:

Handwritten signature of Karl R. Houskeeper

Date Thursday, March 19, 2009

Karl Houskeeper, Environmental Scientist III
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

**2. Signs and Markers**

The mine ID sign is located adjacent to the tipple on a light pole. The MSHA Refuse Pile sign was also checked during the inspection and contained the required information.

**6. Disposal of Excess Spoil, Fills, Benches**

Excess spoil pile #2 remains active. Material continues to be placed on top of the pile and then compacted in lifts.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile is being excavated in various lifts depending on the needed quality for the power plant. The refuse pile appeared stable. No visible hazards were observed.