



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Outgrimes
C0070042
#4067
α

June 5, 2012

Richard Carter
Sunnyside Cogeneration Associates
PO Box 159
Sunnyside Utah 84539

Subject: 2011 Annual Report Review Completion, Star Point Refuse, C/007/0042, Task #4067

Dear Mr. Carter:

The Division staff has completed the review of the 2011 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed on June 4, 2012.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs
Enclosure
cc: Price Field Office
O:\007042.SWF\WG4067\ReviewCompletionLetter.doc



Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by **March 30, 2012**. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Sunnyside Cogeneration Assoc.	Mine Name	Star Point Waste Fuel
Permit Number	C/007/0042	Permit expiration Date	2013-11-14
Operator Name	Rick Carter	Phone Number	+1 (435) 888-4476
Mailing Address	PO Box 159	Email	
City	Sunnyside		
State	UT	Zip Code	84539

DOGM File Location or Annual Report Location

Excess Spoil Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted quarterly to DOGM
Refuse Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted quarterly to DOGM
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	Submitted quarterly to DOGM
Other:		

OPERATOR COMMENTS

All impoundments performed as designed with no discharges during 2011
 The refuse pile is being excavated as intended and in conformance with the approved design
 The Disposal area/Excess Spoil Pile is in conformance with the approved plan

REVIEWER COMMENTS

Met Requirements Did Not meet Requirements

Reviewed by James Owen. Certified quarterly and annual inspection reports for impoundments, refuse pile, and disposal areas is included in Appendix A of the Annual Report submittal. No failures were reported during 2011.

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

Storm water permit was renewed effective 1/1/2012
Two reclaimed areas within the permit boundary are being monitored by RAG in connection with their reclamation reporting. These areas appear to be doing well
SCA excavated 340,854 tons of refuse material from this site and transported it to the Sunnyside facility
No material was placed in the disposal area during 2011

Reviewer Comments

MAPS

Copies of mine maps, current and up-to-date through at least December 31, 2011, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
Mine Map	1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Current mining plan is in the permit	#521.100 d and e	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements

Reviewed by James Owen. An updated version of the Mine Map was included with the Annual Report submittal. The drawing is properly certified. The drawing indicates current and past mining activity as well as contours for areas previously reclaimed.