



Suzanne Steab < [suzannesteab@utah.gov](mailto:suzannesteab@utah.gov) >

---

**RE: Star Point Refuse NOV #10139**

1 message

---

**Rusty** < [rnetz@emerytelcom.net](mailto:rnetz@emerytelcom.net) >

Tue, May 6, 2014 at 1:47 PM

To: "suzannesteab@utah.gov" <[suzannesteab@utah.gov](mailto:suzannesteab@utah.gov)>

Cc: "jamesowen@utah.gov" <[jamesowen@utah.gov](mailto:jamesowen@utah.gov)>, "daronhaddock@utah.gov" <[daronhaddock@utah.gov](mailto:daronhaddock@utah.gov)>, Steve Christensen <[stevechristensen@utah.gov](mailto:stevechristensen@utah.gov)>, Karl Houskeeper <[karlhouskeeper@utah.gov](mailto:karlhouskeeper@utah.gov)>

Daron/James,

This is regarding the NOV Citation # 10139. Under the section of "Actions Required" It lists several actions that SCA needs to complete.

SCA does not believe we will need to update the hydrology section of the SCA permit. Maps 731.720a and 731.720b correctly show the diversion ditch pertaining to the citation. The narrative in Section 7 of SCA's MRP adequately describes the diversion in question ( diversion 7G). Map 731.720b adequately depicts the names and locations of all ditches, diversions, and culverts.

There was some confusion, initially, pertaining to the diversion ditch in question. That was cleared up, at the SCA Plant on May 1, 2014, with Duane Matt of OSM. We were able to show Duane adequate approved maps of all diversions, adequate language, adequate design, and adequate calculations associated with the diversion ditch in question (diversion 7G).

This is not a new diversion, we are not adding a diversion. The diversion is/was existing and approved. It was damaged during the removal of waste fuel and during the process of contouring the slope for future reclamation. We will repair the diversion ditch back to its original design specifications and original location, per SCA's approved MRP. This work will be completed by May 12, 2014.

We will follow up with pictures, and of course it can be inspected on the next monthly DOGM inspection. Please call if my email is not very clear. Thank you.

Rusty Netz  
Sunnyside Cogen.  
(435)888-4476 ext. 107

---

Date: Tue, 6 May 2014 11:06:38 -0600  
Subject: Star Point Refuse NOV #10139  
From: [suzannesteab@utah.gov](mailto:suzannesteab@utah.gov)  
To: [rnetz@emerytelcom.net](mailto:rnetz@emerytelcom.net)  
CC: [jamesowen@utah.gov](mailto:jamesowen@utah.gov); [daronhaddock@utah.gov](mailto:daronhaddock@utah.gov); [stevechristensen@utah.gov](mailto:stevechristensen@utah.gov)

Hello Rusty,

Please see attached.

The original was mailed certified on 5/5/14.

Thanks

--

Suzanne Steab, Engineering Technician II  
Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
Salt Lake City, Utah 84114-5801