



0002

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

November 3, 1986

Mr. Mike O'Donnell
Governmental/Environmental Coordinator
Western States Minerals Corporation
4975 Van Gordon Street
Wheat Ridge, Colorado 80033

Dear Mr. O'Donnell:

Re: Repair Maintenance Items, J. B. King Mine, INA/015/002, Folder No. 3 and 7, Emery County, Utah

This letter is to follow up on our phone conversation of October 31, 1986 and the site visit with Tom Munson, Kathy Mutz and Phil Ralphs on October 28, 1986, regarding work needed at the J. B. King reclamation site. Three items need to be addressed at the site as follows:

1. The main channel between stations 8+00 and 5+30 (Map 4050-514R) should be regraded, banks reshaped, riprap protection with filter blankets installed, and drop structures installed to control head cutting problems.
2. The feeder ditch to the south of the main channel area noted in #1 above is experiencing similar problems and should be addressed as noted in #1 above.
3. Rills formed in the site, particularly on the slopes of the refuse pile, should be repaired by handwork and broadcast seeded by hand.


As we noted in our discussion, detailed plans and descriptions for these items, particularly the channel work, will be forwarded to the Division by November 21, 1986.

Page 2
Mike O'Donnell
INA/015/002
November 3, 1986

The seriousness of this situation is reinforced by the continued deterioration of the channels since our meeting of October 3, 1986.

Thank you for your cooperation in rectifying these concerns.

Sincerely,



John J. Whitehead
Permit Supervisor/
Reclamation Hydrologist

djh
cc: L. Braxton
T. Munson
K. Mutz
P. Ralphs
0800R/57