

0003

112-87



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

*File* *John*

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84140-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: Oct. 6, 1987  
11:00 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Western States Minerals Corp.  
Business Address: 4975 Van Gordon Street Wheat Ridge, Colo. 80033  
Mine Name: J.B. King Permit Number: INA/015/002  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official (s): none  
State Official(s): Harold G. Sandbeck and Bill Malencik, DOGM  
Partial:  Complete:  Date of Last Inspection: Sept. 16, 1987  
Weather Conditions: Clear and warm  
Acreage: Permitted 480 Disturbed 30 Regraded 30 Seeded 30 Bonded 30  
Enforcement Actions: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/015/002

DATE OF INSPECTION Oct. 6, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

On September 16, 1987, DOGM conducted a complete oversight inspection with Joe Funk (OSM). Joe Funk issued four (4) TDN's as noted below:

T87-02-006-009, 1 of 4 - An after pond construction certification statement was not found. This TDN was abated September 30, 1987, because of the operator's timely response to sending a certification before the TDN deadline.

T87-02-006-009, 2 of 4 - Operator failed to construct a permanent stream channel diversion with gently sloping banks stabilized by vegetation. Undersigned inspector field checked and abated this TDN on September 30, 1987.

T87-02-006-009, 3 of 4 - Operator failed to fill, grade, or otherwise stabilize regraded and topsoiled areas. The 20 and 9 inch rills and gullies were repaired and field checked by the undersigned inspector. This TDN was abated September 30, 1987.

T87-02-006-009, 4 of 4 - Operator failed to comply with the terms and conditions of the permit. This TDN was abated using INE-27. The operator was given until October 30, 1987, to revise the mine plan.

On this partial inspection, the undersigned inspector found the site ground conditions in compliance with UMC requirements.

Copy of this Report:

Mailed to: Tom Hughes, WSMC and Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Oct. 7, 1987

*Harold G. Sandbeck*

*received  
11-2-87*