

0014



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

2-26-88

Julie

John  
Dianne

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Feb. 12, 1988  
8:30 a.m. to 10:00 p.m.

Permittee and/or Operators Name: Western States Minerals Corp.  
Business Address: 4975 Van Gordon Street Wheat Ridge, CO 80033  
Mine Name: J.B. King Permit Number: INA/015/002  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official (s): None  
State Official(s): Harold G. Sandbeck and Bill Malencik  
Partial:  Complete:  Date of Last Inspection: Jan. 6, 1988  
Weather Conditions: Clear and warm  
Acreage: Permitted 480 Disturbed 30 Regraded 30 Seeded 30 Bonded 30  
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( X )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( X )	( )
7. COAL PROCESSING WASTE	( )	( )	( X )	( )
8. NONCOAL WASTE	( )	( )	( X )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( X )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( )
12. BACKFILLING AND GRADING	( X )	( )	( )	( )
13. REVEGETATION	( X )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( X )	( )
15. CESSATION OF OPERATIONS	( )	( )	( X )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( X )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( X )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/015/002

DATE OF INSPECTION Feb. 12, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The mine site was frozen and covered with snow. The site had been damaged by a storm as documented in the inspection reports dated November 13, 1987, and December 8, 1987.

On February 1, 1988, DOGM met with Tom Hughes (WSMC's environmental engineer). Tom Hughes presented a number of possible conceptual design repairs. As a group, we were unable to tour the site because the ground was covered with snow. A tentative on-site meeting was scheduled for March 31, 1988. At this on-site meeting, WSMC's conceptual designs will be discussed and commitments agreed upon by WSMC and DOGM. The mine site will be repaired by spring.

No other problems were noted. Cows were seen grazing near the mine site.

Copy of this Report:

Mailed to: Tom Hughes, WSMC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Feb. 16, 1988