

0024



*File Action 1002  
#2  
Copy [unclear]*

February 12, 1991

**RECEIVED**  
FEB 14 1991

DIVISION OF  
OIL, GAS & MINING

Ms. Pamela Grubaugh-Littig  
Division of Oil, Gas & Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Re: J. B. King Mine

Dear Ms. Grubaugh - Littig:

Please find enclosed four copies of a revised map of the J. B. King Mine (JBK-1, Rev.1) which depicts the area reseeded in 1989 and prelaw disturbed areas. We have proposed six additional area markers (i.e., M1-M6) to define that portion of the reseeded area which is not bounded by distinct topographical features.

It is also proposed that disturbed area marker No. 6 be moved up from its present location at the base of the cliff to the location shown on the revised map. We will install the additional markers this spring if their location is acceptable to your agency. Also please find enclosed the following:

1. Correspondence with Utah State Lands and Forestry and the Bureau of Land Management regarding the determination of normal conservation practices for the region.
2. The J. B. King Annual Report

The small gully described in Wes Sorensen's pond certification will be filled in within the next two weeks.

Sincerely,

Frank Filas  
Environmental Engineer

Enclosure

cc: A. Noble