



gjt

pgl

inspection report

Permit No. ACT/015/002

Inspection Date October 3, 1991

Permittee/Operator Name Western States Minerals

Business Address 4975 VanGordon Street

City Wheatridge State Colorado Zip 80033

Mine J.B. King (Reclaimed) Surface Underground Other

County Emery State Utah

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 2:00 a.m. p.m. to 5:30 a.m. p.m. Partial Complete

Date of last inspection September 10, 1991 Weather conditions Clear/Temp. 70° - upper

Acreage 480 Permitted 30 Disturbed Regraded 30 Seeded 30 Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
2. Signs and markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
- Stream channel diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	14. Subsidence control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

WHITE-DOG M YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date October 3, 1991

Please number comments to correspond with topics on previous page.

General Comments: The instant partial inspection found field conditions not
significantly different from maintenance items discussed in the September 10, 1991
inspection by the Division.

The permittee has not initiated any work requested in the 9-10-91 inspection.
However, the permittee has communicated with the Division on a proposal that ties
in to outstanding stipulations.

It would be my suggestion that the maintenance items discussed in the
September 10, 1991 inspection report be completed this fall. The risk, if such
work is not performed, is spring runoff in the concerned diversions and the coal
storage outslope may result in violating performance standards relating to
erosion, coal fines, and erosion control measures.

Discussed the matter with Mr. Blackburn. He advised me that he has not been
given any direction to initiate maintenance work this fall.

Copy of report mailed to WSM/Dwight Crossland, OSM/Brian Smith, DOGM/Joe Helfrich

Copy of report ^{filed} given to PF0

Inspector's signature  October 3, 1991 No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE