



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

John P. [Signature]

INSPECTION REPORT

INSPECTION DATE & TIME: June 12, 1991
11:30 am to 1:30 pm

Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: 4975 Van Gordon St., Wheat Ridge, CO 80033
Mine Name: J.B. King Permit Number: ACT/015/002
Type of Mining Activity: Underground X Surface Other
County: Emery Company Official(s): None
State Officials(s): Susan White, Henry Sauer
Federal Official(s): None
Partial: Complete X Date of last Inspection: May 7, 1991
Weather Conditions: Fair and warm.
Acreage: Permitted 480 Disturbed 30 Regraded 30 Seeded 30
Bonded 30 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 05/12/91

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

Insurance is in order, effective date is December 31, 1990 to December 31, 1991. General aggregate is up to two million and per occurrence coverage is one million.

The annual reports have been submitted. The sediment pond inspection, certified by a Professional Engineer, indicated no problems. Subsidence monitoring was completed for 1990. All movement detected was less than one foot.

Two stipulations are still outstanding and must be resolved by July 15, 1991, or violations will be issued.

All other permit documents appeared in order.

4. HYDROLOGIC BALANCE

The main channel (unarmored) ditch shows erosion near the ditch head. This will require some work.

A few silt fences are also in need of repair.

The second quarter sediment pond inspection has not been submitted. This should be submitted soon after the end of June. It appears that no discharge of the sediment pond has occurred. The pond was dry at the time of inspection.

13. REVEGETATION

Vegetation appears excellent in some areas, such as along the channel, sediment pond, and north facing slope of the refuse pile. Other areas such as the southwest aspect of the refuse pile and ridge north east of the sediment pond have poor vegetative establishment.

It was suggested to the operator to make some attempt to roughen surfaces on the refuse pile to encourage vegetation development.

Copy of this Report:

Mailed to: Dwight Crossland (WSM); John Kathmann (OSM)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Steven M. White* #35 Date: 06/13/91