

0007



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

October 9, 1991

Mr. Dwight Crossland
Western States Minerals Corporation
84 Glen Carran Circle
Sparks, Nevada 89431

Dear Mr. Crossland:

Re: Stipulation Responses, Western States Minerals Company, J.B. King Mine, ACT/015/002, Folder #2, Emery County, Utah

The Division is in receipt of the stipulation responses for the J.B. King Mine. The response and time frames for Stipulations R614-301-120 and R614-301-140 are acceptable. The response time frame for Stipulation R614-301-742.113, however, should be as soon as possible.

We are looking forward to the site meeting with you on Thursday, October 17, 1991. Thank you.

Sincerely,

A large, stylized handwritten signature in black ink, reading 'Pamela Grubaugh-Littig'.

Pamela Grubaugh-Littig
Permit Supervisor

PGL/jbe



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

October 7, 1991

TO: Pamela Grubaugh-Littig, Permit Supervisor

FROM: Susan M. White, Reclamation Biologist *SMW*

RE: Stipulation Response Dated September 30, 1991, Western States Minerals, J. B. King Mine, ACT/015/002, Folder #2, Emery County, Utah

Synopsis and Analysis

The permittee, in addressing Stipulation R614-301-120 and R614-301-140 (JK) has committed to relocating the disturbed area boundaries by October 15, 1991, and submitting a revised map by October 31, 1991.

Stipulation R614-301-742-113 (TM), the permittee states by November 16, 1991, the data collection will end and a proposal of erosion control measures will be submitted to the Division. This submittal is directly related to the erosion damages caused by the September thunderstorms on the property. To date, very little maintenance or repair work has been done on site from these storms and the site is bordering on non-compliance with the permit and coal mining rules.

Recommendation

The response and time frame to Stipulation R614-301-120 and R614-301-140 (JK) is acceptable. The response time frame to Stipulation R614-301-742-113 (TM), considering the possible compliance problems on site, is not acceptable.

jbe
cc: Tom Munson
Jesse Kelley
AT015002.901