



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 5/29/95 9am to 12 pm
Date of Last Inspection: 4/13/95

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002

Permittee and/or Operator's Name: Western States Minerals Corp.

Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502

Type of Mining Activity: Underground X Surface Prep. Plant Other

State Officials(s): Susan White,

Company Official(s):

Federal Official(s): None

Weather Conditions: Partly cloudy and cool

Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 5/29/95

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL

Soil moisture was observed approximately 1 inch below the soil surface.

4. HYDROLOGIC BALANCE:

a. Diversions - No evidence of flow was observed in the channels which were reconstructed in December. No water was in the sediment pond. The operator requested an extension for submittal of as-built until August.

13. REVEGETATION

Germination was observed from the December 1994 seeding. Grass seedlings were observed in almost every depression on the reclaimed refuse pile. Poor germination was observed on the shaley area, on the south end of the site.

Annual weeds were abundant on the site, both native and introduced.

14. SUBSIDENCE

The areas of previous subsidence was walked and no cracks were observed that have not been noted previously. The previously noted areas were mainly rodent burrows.

Copy of this Report:

Mailed to: Tom Ehmett (OSM), E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Aaron M. White* #35 Date: 6/8/95