



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-538-5340 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 4/13/95 10am to 1 pm
Date of Last Inspection: 3/9/95

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002

Permittee and/or Operator's Name: Western States Minerals Corp.

Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502

Type of Mining Activity: Underground X Surface Prep. Plant Other

State Official(s): Susan White,

Company Official(s):

Federal Official(s): None

Weather Conditions: Cloudy, windy and cool

Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 4/13/95

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL

No soil moisture was observed in the top inch of soil. A heavy white precipitate was evident on some of the soil material.

4. HYDROLOGIC BALANCE:

a. Diversions - No evidence of flow was observed. No water was in the sediment pond.

13. REVEGETATION

Very little germination of seed was observed from the 1994 revegetation effort.

In December the operator had dressed and seeded the UDOT borrow site where the gravel mulch had been obtained. At this inspection the UDOT was observed obtaining more material from the site, essentially removing all of the revegetation work.

Copy of this Report:

Mailed to: Tom Ehmett (OSM), E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White

#35 Date: 4/17/95