



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
 Governor
 Ted Stewart
 Executive Director
 James W. Carter
 Division Director

355 West North Temple
 3 Triad Center, Suite 350
 Salt Lake City, Utah 84180-1203
 801-538-5340
 801-359-3940 (Fax)
 801-538-5319 (TDD)

April 26, 1995

TO: Daron Haddock, Permit Supervisor

FROM: Susan M. White, Senior Reclamation Biologist *SMW*

RE: As Built Drawings 1994 Work, J. B. King Mine, Western States Minerals, ACT/015/002, File #2, Emery County, Utah

SYNOPSIS

As built maps of the 1994 site work were submitted, date received April 12, 1995. This memo reviews only those maps, realizing that written support documentation of the site work also needs to be included in the permit.

ANALYSIS

Drawing No: JBK-3 AS BUILT appears to correctly depict the 1994 site work. However, as required by R645-301-542.300 the map must be certified as described under R645-301-512. The map also depicts a zone surrounding the channels as "lateral performance boundary for new channel", without accompanying text the purpose of this zone is not clear.

Four as-built cross section details of the channel reconstruction were submitted, A-A thru D-D. The cross sections are not certified and must be certified as described under R645-301-542.300. The cross sections do not reflect the actual field conditions of vertical cuts for the channel side slopes.

RECOMMENDATION

The maps cannot be approved until they are certified as described in R645-301-542.300. The "lateral performance boundary for new channel" shown on Drawing No: JBK-3 AS BUILT must be defined and the cross sections of the channel, sections A-A thru D-D must reflect on the ground conditions.

cc: Henry Sauer

