

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

January 30, 1997

(Comments are Numbered to Correspond with Topics Listed Above)

The site was mostly snow covered (1 to 3 inches) except for the south facing slopes. Snow remained in some south facing pocks, several inches to a foot deep. Evidence of strong winds where drifts were several feet deep.

4. HYDROLOGIC BALANCE

b. **Sediment Ponds and Impoundments** - The sediment pond appeared to still contain water. The pond surface was covered with ice.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

During this inspection sugar was applied to the cryptogram test plots. No water was applied because of the snow on site. Sugar was applied over the snow.

Several solitary fresh elk tracks were observed on site.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White

35 Date: 2/4/97