



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Handwritten initials 'JF'

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

Partial: X Complete: Exploration:
Inspection Date & Time: 5/27/99, 10:30 a.m. to 2:00 p.m.
Date of Last Inspection: 4/27/99

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002
Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Robert Davidson and Sharon Falvey
Company Official(s):
Federal Official(s):

Weather Conditions: Partly cloudy, warm, and breezy; thunderstorms over the Wasatch Plateau
Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)
REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, Evaluated, N/A, Comments, NOV/ENF. Contains 21 rows of inspection items with checkboxes.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 5/27/99

(Comments are Numbered to Correspond with Topics Listed Above)

SUMMARY:

- Sediment pond is dry.
- Weather and rainfall data was received on 5/12/99 for the period 9/23/98 thru 1/29/99.
- The site is secured with no signs of intrusion since last inspection.

2. SIGNS AND MARKERS

The lower and upper permit entry signs are both in good condition.

4. HYDROLOGIC BALANCE

b. SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond is dry, with the dried cracked sediment in the bottom of the pond.

d. Water Monitoring

Weather and rainfall data for 9/23/98 thru 1/29/99 is summarized as follow:

maximum temp. 77.2 F
Minimum temp. -6.5 F
Total rainfall 2.26 inches
Maximum event 0.17 inches

9. PROTECTION OF FISH, WILDLIFE AND OTHER RELATED VALUES

Both the bottom front and upper entrance gates were secured and closed. There were no cattle in or around the site. There was no new evidence that cattle have been in the site since last month's inspection. The dead elk at the sediment pond is badly decomposed.


13. REVEGETATION

Signs of grass germination were observed on the small parcel adjacent to the North Diversion Ditch where husbandry practices were installed in November 1998.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:  #45 Date: 6/1/99