

June 7, 1978

Memo to File:

Re: Swisher Coal Company
Huntington #4
Emery County, Utah
ACT/015/004

On June 1st 1978, Jim Smith and Brian Buck inspected this active underground coal mine. Mill Fork Creek was flowing a good stream of very murky water at the culvert under the coal haulage road. The road has been regraded and re-ditched after the winter season and is in good shape. The road shoulders have been recently seeded with grass seed.

The creek is being polluted with coal fines along the road. This could be minimized by some drainage control berms along the stream side of the road.

Three water samples were taken above the mine, at the mine discharge and, at the lower culvert.

BRIAN W. BUCK *BWB*
ENGINEERING GEOLOGIST