

ACT/015/004

0004

SCOTT M. MATHESON
Governor



OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES

I. DANIEL STEWART
Chairman

CLEON B. FEIGHT
Director

DIVISION OF OIL, GAS, AND MINING

1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

CHARLES R. HENDERSON
JOHN L. BELL
THADIS W. BOX
C. RAY JUVELIN

June 6, 1978

Mr. Dave Shaver
Swisher Coal Company
P.O. Box AU
Price, UT. 84501

Dear Dave:

On June 1st 1978, Jim Smith and myself visited the #4 mine and noticed how the haul road had been regraded to clean the ditches and the shoulders seeded. We thought the seed might have gone on a little late, but we were favorably impressed.

I do think that you are getting some coal into the creek along the road and suggest that you check the drainage control of the road to control this.

We took a water sample from below the grates at your mine discharge shed. The water was very murky at the time and we wondered if this was normal, please respond.

Sincerely,

BRIAN W. BUCK
ENGINEERING GEOLOGIST

/tlb