

Document Information Form

Mine Number: C/015/004

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: August 28, 1981

Explanation:

Inspection Memo

cc:

File in: C/015, 004, Internal

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

August 28, 1981

Inspection Memo
to Coal File:

RE: Huntington Canyon #4
Beaver Creek Coal Co.
ACT/015/004
Emery County, Utah

The above-mentioned mine operation was given a partial inspection on July 16, 1981, by Dave Lof and Sandy Pruitt of the Division, accompanied by David Meyer, Beaver Creek Coal Company. Several areas of concern were noted during the inspection and requirements documented in a registered letter and was sent to David Meyer on July 21, 1981, immediately following the inspection.

The below listed compliance requirements resulting from the June 12, 1981, inspection by Tom Portle were given a July 30, 1981, deadline.

1. Clean up trash and all noncoal waste and permanently dispose of it as required in UMC 817.89.
2. Prepare SPCC plans in accordance with the Federal Water Pollution Control Act and regulations under Title 40, Chapter I, Subchapter D, Part 112, entitled "Oil Pollution Prevention." Submit the plans to the Division in an addendum to the permanent mine plan required by UMC 782.19. Plans should be implemented immediately or no later than July 30, 1981.
3. The coal stockpile at the middle pad had been washed out by a recent runoff event. Mr. Meyer could not determine if the catch basin above the stockpile had overflowed or if the bypass culvert had been obstructed. It was requested that the gully be filled, graded and stabilized as required under UMC 817.106. The inlet to the sediment pond should also be stabilized by August 16, 1981.

Following the July 16th inspection, the below listed compliance requirements were given an August 16, 1981 deadline.

1. Remove timbers being temporarily stored outside of the disturbed area perimeter and store at a site prepared for compliance under UMC 817.42(a)(1).
2. Maintain surface grade berms and undisturbed drainage channels and culverts to meet design and maintenance requirements under UMC 817.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0006 Date 8-28-81
In C/ 015, 004, Internal

For additional information

As the writing of this memo has been delayed, this inspector is aware that two inspections have been subsequently conducted and all of the above listed compliance requirements have been addressed.

SANDY PRUITT *SP*
RECLAMATION OFFICER

cc: Tom Ehmett, OSM
David Meyer, Beaver Creek Coal
Inspection Staff

SP/btm

Statistics:

See Soldier Creek Canyon memo dated July 28, 1981
Grant: A & E