

0015

BEAVER CREEK Coal Company
P. O. Box AU
Price, Utah 84501
Telephone 801 637-5050

Copy to Sally Andy
FILE 015/004



February 18, 1982

Ms. Sally Kefer
Utah Div. of Oil, Gas & Mining
4241 State Office Building
Salt Lake City, Utah 84114

Re: Huntington Canyon #4 Mine
Sediment Ponds Modification
ACT/015/004

DIVISION OF
OIL, GAS & MINING

RECEIVED
FEB 19 1982

Dear Sally:

As per your letter of 12/1/81 approving our modification of the #4 Mine sediment ponds, the following information is submitted in compliance with your stipulations.

1. Beaver Creek Coal Company will review the operational need and capability of this system by 5/1/82 to justify its further use or non-use.
2. A 12" cpm culvert has been used as a de-watering device.
3. As we discussed by telephone, no discharge has occurred as of this time; therefore, we cannot estimate the rate of de-watering from the upper to lower cell as requested. This will be done as soon as possible after start up of discharge.
4. Mine water discharge and treatment will be carried out during operating hours at Huntington #4 Mine when the discharge starts.

We appreciate your cooperation in expediting this approval. We have found that after getting the water under control underground it could be recirculated for the mining operation cutting down on the immediate need for discharge. The possibility of discharge still exists, and we will notify the State when and if this does occur.

Very truly yours,

BEAVER CREEK COAL COMPANY

Dan W. Guy
Engineering Manager

DWG/daf

cc: File BEAVER CREEK Coal Company is a Subsidiary of AtlanticRichfieldCompany