

April 21, 1983

Inspection Memo  
to Coal File:

RE: Beaver Creek Coal Company  
Huntington #4 Mine  
ACT/015/004  
Folder No. 7  
Emery County, Utah

On April 14, 1983 John Whitehead performed a partial inspection at the above noted minesite accompanied by Scott Raymond of Beaver Creek Coal Company. The primary purpose of the inspection was to orient this inspector to the minesite as this was his first inspection there.

The sediment pond discharge outlet which flows into Mill Fork Creek could not be seen and may be covered by material generated by snow removed. This will be checked during the next inspection to clarify if in fact the culvert outlet will be exposed by melting snow or will require maintenance. No other enforcement problems were observed.



JOHN J. WHITEHEAD  
FIELD SPECIALIST

JJW/lm

cc: Tom Ehmett, OSM  
Scott Raymond, BCCC  
Joe Helfrich, DOGM

Statistics:

See Knight Mine memo dated April 19, 1983.