

February 8, 1983

#7

Memo to Coal File:

RE: Huntington #4 Mine
Beaver Creek Coal Company
ACT/015/004
Emery County, Utah

Sandy Pruitt and Scott Raymond conducted an inspection of the above mentioned operation on January 19, 1983. On-site compliance appeared very good, the mine access road had been recently graded and culverts maintained. A storage site for snow removed off the road has been established near the cyclone that should prevent disposal into Miller Creek. The sediment pond cleaning operation was completed and it does not appear that a pond discharge will occur for some time.

SANDY PRUITT
FIELD SPECIALIST

SP/lm

cc: Tom Ehmett, OSM
Scott Raymond, BCCC
Joe Helfrich, DOGM

Statistics:

See Gordon Creek #2 Mine memo dated February 8, 1983.