


0006

Beaver Creek Coal Company

FILE

ACT/015/004,

2



*Copies distributed week of
Nov. 19th MB*

November 12, 1984

Mary M. Boucek
Permit Supervisor
Utah Division of Oil, Gas, & Mining
4241 State Office Building
Salt Lake City, UT 84114

RE: Technical Deficiencies
Beaver Creek Coal Company
Huntington Canyon No. 4 Mine
ACT/015/004, #2
Emery County, Utah

Dear Mary:

Attached are 15 copies of the Beaver Creek Coal Company response to the Technical Deficiency letter of October 19, 1984. Also attached is a checklist showing response locations to each comment. All sheets and maps are provided as replacements or additions to the existing plan - old sheets or maps with duplicate numbers should be discarded after replacement with the new sheets provided.

If you have any questions, or need any further information, please let me know.

Respectfully,

Dan W. Guy
Manager of Permitting and Compliance

DWG/sb

Attachments

cc: J.A. Herickhoff (without attachments)
C.W. McGlothlin (without attachments)
W.L. Craig (without attachments)
File 4-P-6-1-1

RECEIVED

NOV 19 1984

**DIVISION OF
OIL, GAS & MINING**