

0014

May 15, 1984

Inspection Memo
to Coal File:

RE: Beaver Creek Coal Company
Huntington #4 Mine
ACT/015/004, Folder #7
Emery County, Utah

A partial inspection was conducted on April 17, 1984 by Barton Kale of the Division. The inspector was accompanied by Dan Guy of Beaver Creek Coal Company.

The mine is continuing to be pillared. As a result mine equipment is continuously removed from underground. Recent bad weather has curtailed transports from removing equipment so the mine yard is becoming quite crowded.

The berm around the diesel fuel tank, at the loadout area is solid. This is evident through the amount of fuel spilled and contained within its boundary. It was requested that the diesel be removed so that in case of a berm failure the fuel does not end up in the sediment pond (which is a NPDES discharge point). According to a phone conversation on May 3, 1984, with Scott Raymond the fuel had been soaked up and removed.


Barton Kale
Mining Field Specialist

BK:re

cc: Dan Guy, BCCC
Jodie Merriman, OSM
Joe Helfrich, DOGM
Mary Boucek, DOGM

Statistics: See Gorden Creek #3&6 mines memo dated May 8, 1984
88610