



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

RECEIVED
JUN 27 1988

AMENDED

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

INSPECTION REPORT

DIVISION OF
OIL, GAS & MINING

INSPECTION DATE & TIME: June 8, 1988
1:30 to 3:30 p.m.

Permittee and/or Operators Name: Beaver Creek Coal Co.
Business Address: P.O. Box 1378 Price, UT 84501
Mine Name: Huntington Canyon #4 Permit Number: INA/015/004
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official (s): _____
State Official(s): Bill Malencik and Bill Warmack
Partial: Complete: Date of Last Inspection: May 3, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 2600 Disturbed 12.5 Regraded 12 Seeded 12 Bonded 12.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	(X)	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	(X)
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/015/004

DATE OF INSPECTION June 8, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

Five-year permit was issued April 29, 1985 and expires April 28, 1990, involving 717.5 acres and is currently bonded for \$360,104. There are no outstanding or pending stipulations. Phase II bond release was approved on November 10, 1986. A recent proof of liability insurance document was reviewed, dated January 1, 1988. It was with Insurance Co. of North America and the term is for the life of the permit.

3. TOPSOIL:

The silt fence from the lower end of the of topsoil pile was removed as requested in the last inspection.

4b. DIVERSIONS:

Some handwork was evident on ditches that had protection, but the protection in the form of addition riprap was added as an additional protective measure. Pumphouse drainage was redirected as requested.

12. BACKFILLING AND GRADING:

Item 5, page 2 of the May 3, 1988 inspection report, i.e., resloping the reclaimed highwall, is scheduled to be done this fall.

13. REVEGETATION:

In areas where the vegetation is somewhat sparse, the operator has collected soil samples within the growth medium and they are currently being analyzed. The vegetation on the reclaimed site is excellent; however, interspersed are small areas - most being 12' x 12' or less - where for an unknown reason the vegetation is not as dense and vigorous as on the remaining areas.

Copy of this Report:

Mailed to: Dan Guy, Beaver Creek Coal

Mailed to SLC for: Brian Smith, DSM; Joe Helfrich, DOGM

Filed to: PFO



Inspectors Signature and Number: William J. Malencik #26 Date: June 20, 1988