

0007



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 11, 1989
1:00 to 4:00 p.m.

Permittee and/or Operators Name: Beaver Creek Coal Company
Business Address: P. O. Box 1378 Price, Utah 84501
Mine Name: Huntington #4 Mine Permit Number: INA/015/004
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Dan Guy
State Official(s): Henry Sauer
Partial: Complete: Date of Last Inspection: June 21, 1989
Weather Conditions: Warm and sunny
Acreage: Permitted 2600 Disturbed 12.5 Regraded 12.0 Seeded 12.0 Bonded 12.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: INA/015/004

DATE OF INSPECTION July 11, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS
2. SIGNS AND MARKERS
3. TOPSOIL
4. HYDROLOGIC BALANCE
 - a. STREAM CHANNEL DIVERSIONS
 - b. DIVERSIONS
 - c. SEDIMENT PONDS AND IMPOUNDMENTS
 - d. OTHER SEDIMENT CONTROL MEASURES
 - e. SURFACE AND GROUNDWATER MONITORING
 - f. EFFLUENT LIMITATIONS
5. EXPLOSIVES
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL
- d. COAL PROCESSING WASTE
8. NONCOAL WASTE
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES
10. SLIDES AND OTHER DAMAGE
11. CONTEMPORANEOUS RECLAMATION
12. BACKFILLING AND GRADING
13. REVEGETATION
14. SUBSIDENCE CONTROL
15. CESSATION OF OPERATIONS
16. ROADS
 - a. CONSTRUCTION
 - b. DRAINAGE CONTROLS
 - c. SURFACING
 - d. MAINTENANCE
17. OTHER TRANSPORTATION FACILITIES
18. SUPPORT FACILITIES UTILITY INSTALLATIONS

: Copy of this Report:

Mailed to: Brian Smith (OSM) and Dan Guy (BCCC)

Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: Henry Sauer #32

Date: 7/11/89

Henry Sauer

7/21/89

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: INA/015/004

DATE OF INSPECTION July 11, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Dan Guy of Beaver Creek Coal Company accompanied the undersigned inspector on this partial inspection of the mine site. Weather conditions were warm and sunny. No evidence of recent precipitation events existed.

4. Hydrologic Balance: Diversions The diversions in and around the lower pad area were inspected and found in good condition. Culverts were inspected and found to be functioning properly and in good condition.
- 4c. Hydrologic Balance: Sediment Ponds and Impoundments All sediment ponds and sediment traps were dry. Embankments and spillways appear structurally sound.
13. Revegetation: The bare areas which were reseeded in the Fall of 1988 seem to be revegetating well. It was noted that heavy deer and elk traffic (evidenced by deer and elk droppings) has occurred on the upper access road. Additionally, the animals seem to be browsing heavily on the new shoots of the seeded and transplanted shrub species.

djh
AT43/39-41