



Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

May 12, 1989

Mr. George Morris
Forest Supervisor
U.S. Forest Service
Manti-LaSal National Forest
599 West Price River Road
Price, Utah 84501

Dear Mr. Morris:

Re: Defect in Permit Application Package, Beaver Creek Coal
Company, Huntington #4 Mine, ACT/015/004-88C, Folder #2,
Emery County, Utah

Division staff identified a defect in the approved Permit Application Package (PAP) for the Huntington #4 Mine. The identified defect was associated with a permit change designated ACT/015/004-88C, that was approved during January 1989. Division staff mistakenly overlooked the need for the approved PAP to include engineered designs for the subject diversion as required by UMC 817.43.

In order to rectify this defect, the operator has submitted the required designs for inclusion in the approved PAP. The attached materials should be used to update your file copy of the approved PAP.

Sincerely,

Richard V. Smith

Richard V. Smith
Acting Permit Supervisor

djh
Attachment(s)
cc: L. Braxton, DOGM
J. Helfrich, DOGM
T. Munson, DOGM
AT8/53



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

May 12, 1989

Mr. Robert Hagen, Director
Office of Surface Mining
Reclamation and Enforcement
Albuquerque Field Office
Suite 310, Silver Square
625 Silver Avenue, S. W.
Albuquerque, New Mexico 87102

Dear Mr. Hagen:

Re: Defect in Permit Application Package, Beaver Creek Coal
Company, Huntington #4 Mine, ACT/015/004-88C, Folder #2,
Emery County, Utah

Division staff identified a defect in the approved Permit Application Package (PAP) for the Huntington #4 Mine. The identified defect was associated with a permit change designated ACT/015/004-88C, that was approved during January 1989. Division staff mistakenly overlooked the need for the approved PAP to include engineered designs for the subject diversion as required by UMC 817.43.

In order to rectify this defect, the operator has submitted the required designs for inclusion in the approved PAP. The attached materials should be used to update your file copy of the approved PAP.

Sincerely,

Richard V. Smith

Richard V. Smith
Acting Permit Supervisor

djh
Attachment(s)
cc: L. Braxton, DOGM
J. Helfrich, DOGM
T. Munson, DOGM
AT8/53



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

May 12, 1989

Mr. Peter A. Rutledge, Chief
Division of Federal Programs
Western Field Operations
Office of Surface Mining
Brooks Towers, 1020 15th Street
Denver, Colorado 80202

Dear Mr. Rutledge:

Re: Defect in Permit Application Package, Beaver Creek Coal
Company, Huntington #4 Mine, ACT/015/004-88C, Folder #2,
Emery County, Utah

Division staff identified a defect in the approved Permit Application Package (PAP) for the Huntington #4 Mine. The identified defect was associated with a permit change designated ACT/015/004-88C, that was approved during January 1989. Division staff mistakenly overlooked the need for the approved PAP to include engineered designs for the subject diversion as required by UMC 817.43.

In order to rectify this defect, the operator has submitted the required designs for inclusion in the approved PAP. The attached materials should be used to update your file copy of the approved PAP.

Sincerely,

Richard V. Smith
Acting Permit Supervisor

djh
Attachment(s)
cc: L. Braxton, DOGM
J. Helfrich, DOGM
T. Munson, DOGM
AT8/53