

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/004

DATE OF INSPECTION: 1/12/95

(Comments are Numbered to Correspond with Topics Listed Above)

The Division is currently seeking OSM's approval for Phase II bond release for this site. The road into Mill D Canyon was covered with a foot to three feet of snow. No vehicles had accessed the site since the last snow storm. The main road in Huntington Canyon was closed above the Genwal Mine because of avalanches. This inspector accessed the site on cross country skis. The upper road was not walked because of the snow depth. The lower site had a one to two feet of snow and the upper road had about 12 to 18 inches of snow.

2. SIGNS AND MARKERS

The permit signs were in place and contained the correct information.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

Deer and elk track were numerous on the lower portion of the Forest Service road, although none since the most recent snow. Further up the canyon evidence of deer and elk was much less than observed on the November and December inspections.

Copy of this Report:

Mailed to: Tom Ehmett (OSM), Paige Beville(MCC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White #35 Date: _____