

1997 Annual Report


Huntington Canyon No. 4 Mine

INA/015/004

Mountain Coal Company
West Elk Mine
Post Office Box 591
Somerset, Colorado 81434
Telephone 303 929-5015



Mary Ann Wright
Associate Director of Mining
Utah Coal Regulatory Program
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801



Re: *Submittal of 1997 Annual Reports*
Huntington Canyon No. 4 Mine
INA/015/004; Folder #2
Emery County, Utah

Dear Ms. Wright:

Enclosed are 2 copies of the Annual Report for 1997 for the Huntington Canyon No. 4 Mine.

The report is filed in the format provided by the Division.

Sincerely,

Dan W. Guy
for
Paige B. Beville

cc: *Paige Beville*
File

GENERAL INFORMATION

1. Permit Number	INA/015/004
2. Mine Name	Huntington Canyon No. 4 Mine
3. Permittee Name	Mountain Coal Company
4. Operator Name (if other than Permittee)	
5. Permit Expiration Date	04/30/2000
6. Company Representative, Title	Paige B. Beville,
7. Phone Number	(303) 293-7913
8. Fax Number	(303) 293-4073
9. Mailing Address	Mountain Coal Company
	P.O. Box 591
	Somerset, Colorado 81434
10. Resident Agent, Title	The Corp Trust Co.
Mailing Address	1209 Orange Street
	Wilmington, DE 19801

IDENTIFICATION OF OTHER PERMITS

Identify other permits which are required in conjunction with mining and reclamation activities.

Permit Type	ID Number	Description	Expires on
1. MSHA Mine ID(S)	N/A		
2. MSHA Impoundment(s)	N/A		
3. NPDES/UPDES Permit(s) (water)	N/A		
4. PSD (Air) Permit(s)	N/A		
5.			
6.			

APPENDIX A

Certified Reports

Excess Spoil Piles
Refuse Piles
Impoundments

as required under R645-301-514

CONTENTS

None

APPENDIX B

Reporting of Technical Data

including monitoring data, reports, maps, and other information
as required under the approved plan
or as required by the Division

in accordance with the requirements of R645-301-130 and R645-301-140.

CONTENTS

Subsidence Inventory Letter

SUBSIDENCE INVENTORY LETTER

**ENVIRONMENTAL INDUSTRIAL SERVICES**

435-472-3814 • 800-641-2927 • FAX 435-472-8780 • EIS@CASTLENET.COM • 31 NORTH MAIN STREET HELPER, UTAH 84526

NOVEMBER 6, 1997

TO: BLACKHAWK ENGINEERING

ATTN: DAN GUY, P.E.

RE: SUBSIDENCE INVENTORY OF NO. 4 MINE

Dear Mr. Guy:

On October 9, 1997, a thorough helicopter aerial survey, in conjunction with the removal of the radio tower on the knoll above number 4 mine and the Genwal mine, was conducted. In addition, a cursory ground survey of the ridge above number 4 mine. The intent of the ground work was to confirm spring flows and look for any irregularities in vegetation that could not be observed from the air but could indicate ground movement, potentially the result of subsidence.

Two small areas of slippage were observed. However, it was obvious they were related to saturated soils in the areas of the Cow Trough Spring and the lower Aspen Spring.

No subsidence was observed and spring flows appeared somewhat greater than the 1996 inventory revealed.

If I can answer any additional questions, please feel free to call me.

Sincerely,

Melvin A. Coonrod
Principal Consultant/Owner EIS

APPENDIX C

Legal, Financial, Compliance and Related Information
Annual Report of Officers
as submitted to the Utah Department of Commerce
and other changes in ownership and control information
as required under R645-301-110.

CONTENTS

No Change

APPENDIX D

Mine Maps

as required under R645-301-525.270.

CONTENTS

N/A

APPENDIX E

Other Information

in accordance with the requirements of R645-301 and R645-302.

CONTENTS

None