



STATE OF UTAH

Notice of Violation No. N

85-2-4-2

Violation No. 1 of 2

Nature of the Violation

Failure to protect topsoil stockpile from wind and water erosion.

Provision(s) of the Regulations, Act, or Permit Violated

UMC 817.23(b)

UCA 40-10-172(e)

Portion of the Operation to which Notice Applies

Topsoil stockpile.

Remedial Action Required (including interim steps, if any)

1. Provide and maintain effective soil stabilization measures until an effective vegetative cover is established to minimize wind erosion.
2. Reestablish and maintain a ditch and berm around the entire base of the stockpile.

Time for Abatement (including time for interim steps, if any)

Two week or no later than 4/4/85.



STATE OF UTAH

Notice of Violation No. 85-2-4-2

Violation No. 2 of 2

Nature of the Violation

Failure to pass all surface drainage from a disturbed area through a sediment pond or treatment facility to prevent additional contributions of suspended solids to runoff leaving the permit area.

Provision(s) of the Regulations, Act, or Permit Violated

UMC 817.42(a)(1)
UMC 817.45
UCA 40-10-18(2)(i)(ii)

Portion of the Operation to which Notice Applies

Gravel storage area located next to the mine identification sign at the beginning of the mine access road.

Remedial Action Required (including interim steps, if any)

Submit plans and obtain DGRM approval of alternative sediment control measures providing adequate containment and/or treatment of runoff from the small gravel storage area. Plans must address requirements of UMC 817.42(a)(3) or relocate the gravel ~~to~~ within the disturbed area drainage boundaries for the mine sediment pond or ~~at the~~ utilize the gravel as road base for maintenance of the road surface.
Time for Abatement (including time for interim steps, if any) Two weeks or by 4/4/85.