



12-28-87

0001

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

gn

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Dec. 8, 1987
1:00 p.m. to 4:00 p.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue Colton, CA 92324-0514
Mine Name: Hidden Valley Permit Number: INA/O15/007
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): None
State Official(s): Harold G. Sandbeck and Brent Stettler
Partial: Complete: Date of Last Inspection: Oct. 21, 1987
Weather Conditions: Clear and cool
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	(X)	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/015/007

DATE OF INSPECTION Dec. 8, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

No significant mine site erosion was observed. Ground conditions were dry.

4a. STREAM CHANNEL DIVERSIONS:

As mentioned in previous inspection reports, the channel had been repaired and was stable. No problems were encountered.

4d. OTHER SEDIMENT CONTROL MEASURES:

The silt fences had been repaired. Some fences were repaired by increasing the fence height. This increase in height may cause stability problems later. The undersigned inspector will monitor the silt fences.

4e. SURFACE AND GROUNDWATER MONITORING:

The September semi-annual surface water sampling results were received by DOGM November 23, 1987, and checked by the undersigned inspector.

16b. ROAD DIVERSIONS:

At this time, the haul road outslopes were stable but need to be watched for any future erosion.

Copy of this Report:

Mailed to: California Portland Cement; Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Dec. 10, 1987