



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

0005

John

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Aug. 9, 1988
2:00-3:00 p.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue Colton, CA 92324-0514
Mine Name: Hidden Valley Permit Number: ACT/015/007 7085
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): None
State Official(s): Bill Warmack and John Whitehead
Partial: Complete: Date of Last Inspection: July 6, 1988
Weather Conditions: Clear and hot
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	(X)	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	()	()	(X)	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	(X)	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION Aug. 9, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The mine site conditions were moist; some evidence was present indicating a previous localized storm had occurred with little or no effects to the site. In maintenance areas noted, some minor hand work is required to reduce future storm impacts. Ivie Creek was flowing during this inspection.

2. SIGNS AND MARKERS:

A new mine I.D. sign was installed and erected on the property. Although the metal post and sign appear to be stable at this time, future installations should be directed towards reducing post height; the current height tends to be very susceptible to the varying winds associated with this area.

4b. DIVERSIONS:

1. Second waterbar diversion upwards from lower road switchback is developing some minor erosion on outslope bank.
2. Road drainage ditch by lower switchback has developed some cutting.

4d. OTHER SEDIMENT CONTROL MEASURES:

1. The silt fences were observed and with the following exceptions, were noted to be in good repair.
 - A. Lower silt fence on the old pond site had some water run around the outer edge of fencing.
 - B. A small piping hole has developed on the southern end of the eastern silt fence along main channel.
 - C. Some water run around has occurred on the southern end of the western silt fence along main channel.
2. The backfill area adjacent to the old pond site, specifically by the rock check dams, is developing some rills especially where the water cascades down from upper dams. Some additional placement of rock may be required to dissipate the water energy in these particular areas.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION Aug. 9, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

4e. SURFACE AND GROUND WATER MONITORING:

The results of the May 1988 stream monitoring work of Ivie Creek were received by the Division on July 18, 1988. Samples were taken on May 23, 1988.

Copy of this Report:

Mailed to: John Rains, California Portland Cement

Mailed to SLC for: Brian Smith, DSM; Joe Helfrich, DQGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: Aug. 12, 1988

William A. Warmack