

0012

2-26-88



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

gch

ju

Norman H. Bangertter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Feb. 12, 1988
10:00 a.m. to 1:00 p.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue Colton, CA 92324-0514
Mine Name: Hidden Valley Permit Number: INA/015/007
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): None
State Official(s): Harold G. Sandbeck and Bill Malencik
Partial: Complete: Date of Last Inspection: Jan. 6, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	(X)	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	()	()	(X)	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	(X)	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/015/007

DATE OF INSPECTION Feb. 12, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Ground was frozen and covered with snow.

2. SIGNS AND MARKERS:

The main entrance sign at the end of the blacktop road was down. Apparently, the post was weakened from bullet holes and then pushed or blown down. The operator will erect the sign as soon as possible.

No other problems were noted.

Copy of this Report:

Mailed to: John Rains, CPC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Feb. 16, 1988