



- Partial
- Complete
- Exploration

Inspection Date: Feb 2, 1996
 Time: 9 : 00 am pm to 2 : 00 am pm
 Date of Last Inspection: 1/26/96

Mine Name: Hidden Valley County: Emery Permit Number: Act 015/007

Permittee and/or Operator's Name: Consolidated Coal Co.

Business Address: 12755 Olive Blvd, St. Louis, Mo 63141

Type of Mining Activity: Underground Surface Prep. Plant Other

State Officials(s): Bill Malencik

Company Official(s): N/A

Federal Official(s): N/A

Weather Conditions: Overcast/Snowing lightly/Windy

Existing Acreage: Permitted- 950 Disturbed- 7 Regraded- _____ Seeded- _____ Bonded- 7

Increased/Decreased: Permitted- _____ Disturbed- _____ Regraded- _____ Seeded- _____ Bonded- _____

Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability 1996 Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

inspection report

INSPECTION REPORT COMMENTS

Permit No. Act 015/007

Inspection Date 2/2/96

Please number comments to correspond with topics on previous page.

General Comments A partial inspection was conducted at the Hidden Valley mine. Received a report from the USF&WS about the Bald Eagle. The undersigned observed on the reclaimed B coal seam. The Eagle was dead. USF&WS from Cedar City on 2/1/96 attempted to locate and secure the eagle. However, they did not find the Eagle.

On 2/2/96 associated with a partial inspection I secure the Eagle and notified USF&WS. They advised me they would pickup the Eagle on 2/5/96.

Environmental Control Measures. The environmental control measures were observed on the mine as noted on page 1. Conditions were no different than reported on the prior inspection report.

Photographs. Photographs of the Eagle and the B coal seam are included as an enclosure to this report.

The Eagle was released to Gary H. Young, USF&WS on 2/5/96

Copy of report mailed to CCC/Kirschbaum; DSM/Petta; DOSM/Helfrich; USF&WS/Gary Young

Copy of report given to Bill Brin Field Office

Inspector's signature [Signature]

No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE OPERATOR GOLDENROD - NOV FILE

2/5/96

WHAT: ATTACHMENT TO HIDDEN VALLEY INSPECTION REPORT
REPORT/PHOTOS PRINTS - DEAD BALD EAGLE

WHO: Found by undersigned while on a routine inspection of the Hidden Valley Mine.

WHEN: January 26, 1996



WHERE: Hidden Valley Mine, Emery County, Utah, Reclaimed Mine B Coal Seam, about 100 yards from Ivie Creek

OTHER:

- Eagle picked up by undersigned on January 2, 1996.
- Eagle released to Gary Young, U.S. Fish and Wildlife Service on January 5, 1996.
- Mr. Young estimated the eagle was about 2½ years of age and showed some classic signs of being poisoned.
- Undersigned did not see any "animal bait" on the mine site.
- The open range area adjacent to the reclaimed mine site is grazed by cattle during the winter and extending into early spring grazing season.
- Most of the mine site, except for the upper end is enclosed by natural barriers and supplemented by barb wire drift fences.
- The nearest source of water is Ivie Creek, perennial stream that transects the reclaimed mine site.

PHOTOS/HIDDEN VALLEY MINE/DEAD BALD EAGLE

GENERAL VIEW OF RECLAIMED B SEAM



PHOTOS/HIDDEN VALLEY MINE/DEAD BALD EAGLE

