



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

NDH

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Michael O. Leavitt
Governor
Lowell P. Braxton
Division Director

Partial: XXX Complete: Exploration:
Inspection Date & Time: 4/15/99 / 10:30a.m.-2:30p.m.
Date of Last Inspection: 3/10/99

Mine Name: Hidden Valley Mine County: Emery Permit Number: ACT/015/007
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 566, Sesser, Illinois 62884
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): None
State Officials(s): Bill Malencik Federal Official(s): None
Weather Conditions: Clear, 50's
Existing Acreage: Permitted- 950 Disturbed- 7 Regraded- Seeded- Bonded- 7
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability 1986 Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 list various permit conditions and their evaluation status.

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 4/15/99

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

A partial inspection of the Hidden Valley reclaimed mine site was conducted by the undersigned.

SUMMARY

No violations were issued. The environmental control measures appear to meet the coal rule performance standards.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were stable and showed no evidence of recent runoff. The diversion above the "A" seam maintained this past summer, meets performance standards. Some fine material from the escarpment is being deposited in the diversion, but doesn't constitute a concern at this point in time.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The MRP requires water monitoring at high and low flow. The sampling on Ivie Creek above and below the mine are to be taken in May and September. The last sampling was taken September 21, 1998.

8. NONCOAL WASTE

The noncoal waste on the surface is not a problem. The exception is at the end of the county road. However, no noncoal waste, pop cans, etc. were observed during the instant inspection.

12. BACKFILLING AND GRADING

As previously documented in prior inspection reports, the "B" seam was regraded in 1997.

13. REVEGETATION

Seedlings we observed from last years rehabilitation efforts. The seedlings are most numerous in the regraded depression areas.

21. BONDING AND INSURANCE

Insurance expires 11/5/99. The surety bond is on records for \$90,758.00 and no bond release has been approved by the Division.

OTHER

Annual report for 1997 was submitted to the Division on 3/26/98.


Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Tim Kirschbaum (Consol) Henry Austin (OSM)

Given to: Joe Helfrich (DOGM) Filed to: Price Field Office

Date: April 16, 1999

Inspector's Signature:  #26

Wm. J. Malencik