

0019



United States Department of the Interior  
OFFICE OF SURFACE MINING  
Reclamation and Enforcement

Brooks Towers  
1020-15th Street

DENVER, COLORADO 80202

*Joe  
John*

April 4, 1980

Mr. Ron Daniels  
Coordinator of Mined Land Development  
Department of Natural Resources  
1588 North West Temple  
Salt Lake City, Utah 84116

**RECEIVED**  
APR 09 1980

DIVISION OF  
OIL, GAS & MINING

Dear Mr. Daniels:

Enclosed please find copies of on-site inspection reports. The inspections were conducted within Trail Mountain Mine during the period of March 12, 1980.

If you have any questions or problems, please contact this office.

Sincerely,

*Murray I. Smith*

Murray I. Smith  
Chief, Division of Inspection & Enforcement

REGIN V ON-SITE INSPECTION REPORT

TRAIL MOUNTAIN COAL COMPANY  
TRAIL MOUNTAIN MINE  
P.O. Box 356  
Orangeville, Utah 84537  
(801) 748-2140

DATE: March 12, 1980  
TIME: 10:00 a.m.  
WEATHER: Sunny, cool, snowfall preceding evening  
COUNTY & STATE: Emery County, Utah  
COMPANY OFFICIAL: Dan Hanna  
STATE OFFICIALS: Joe Helfrich and Doug Stewart  
OSM OFFICIALS: Larry Damrau and Tom Anderson  
STATE PERMIT NO: ACT/015/009  
MSHA I.D. NUMBER: 42-01211  
STATE ENFORCEMENT  
ACTIONS: Notice of Violation, letter dated February 22, 1979.  
FEDERAL ENFORCEMENT  
ACTIONS: NOV #79-5-5-3 and NOV #80-5-3-2

A follow-up inspection to evaluate remedial action required under NOV #80-5-3-2 was conducted. Surface drainage had been directed into small sump areas adjacent to the access road. With proper maintenance of the facilities, surface drainage should enter the sumps prior to discharging off of the affected area. Straw bales are also being installed at the point where the sumps would discharge.

Notice of Violation #80-5-3-2, violation #1 of 1, was terminated following the inspection.

  
LARRY DAMRAU  
RECLAMATION SPECIALIST