



STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF WATER RIGHTS

DEE C. HANSEN
STATE ENGINEER

EARL M. STAKER
DEPUTY

200 EMPIRE BUILDING
231 EAST 400 SOUTH
SALT LAKE CITY, UTAH 84111
(801) 533-6071

DIRECTING ENGINEERS
HAROLD D. DONALDSON
DONALD C. NORSETH
STANLEY GREEN
ROBERT L. MORGAN

April 3, 1980

Mr. K. Michael Thompson
Division of Oil, Gas and Mining
1588 West North Temple
Salt Lake City, Utah 84116

Re: Trail Mountain Coal Company Outlet Control Structure for Existing
Sedimentation Pond

Dear Mr. Thompson:

This office has completed its review of the above mentioned project, and approve of the design. I would suggest that the 18 inch CMP outlet pipe have at least one cutoff collar and that the forces that will be concentrated at the 45° elbow be checked to see if a thrust block is needed to prevent movement.

Sincerely,


Dee C. Hansen, P.E.
State Engineer

DCH:RLM:sn