

0023



FILE ACT/015/009
FOLDER #7

SCOTT M. MATHESON
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS, AND MINING
1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

CHARLES R. HENDERSON
Chairman

CLEON B. FEIGHT
Director

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

Modification of Notice or Order

To the Following Permittee or Operator:

Name DIAMOND SHAMROCK COAL UNIT - TRAIL MOUNTAIN COAL CO.

Mailing Address P.O. Box 551 ORANGEVILLE, UT

State Permit No. ACT/015/009

Utah Coal Mining and Reclamation Act, Section 40-10-1 et. seq., Utah Code Annotated (1953):

Notice of Violation No. N 84-4-6-3 Y APRIL 18 TV dated APRIL 18, 1984.

Cessation Order No. C _____ Y _____ TV dated _____, 19_____.

Violation No. 1 is modified as follows:

The reason for this modification are as follows:

Violation No. _____ is modified as follows:

The reasons for this modification are as follows:

Violation No. _____ is modified as follows:

The reasons for this modification are as follows:

Date of Service MAY 2, 1984

David Loe
Signature of Authorized Representative

Time of Service or Mailing 4:40 a.m. X p.m.

DAVID LOE #4
Name and I.D. No.

REMEDIAL ACTION REQUIRED: MORE SPECIFIC REQUIREMENTS

1. ENSURE THAT THE EMERGENCY ~~SPILLWAY~~ SPILLWAY IS AT THE PROPER HEIGHT IN RELATION TO THE Dewatering DEVICE AND TOP OF THE SEDIMENT POND EMBANKMENT
2. REMOVE THE HINGED STEEL PLATE FROM THE TOP OF THE 48" RISER
3. PLUG AND SEAL THE EIGHT (8) 4" x 3.5" HOLES CUT NEAR THE TOP OF THE 48" RISER
4. INSTALL A SLOTTED STEEL PLATE TRASH RACK ON TOP OF THE ANTI-VORTEX COLLAR (SEE FIGURE 7-13 "SEDIMENT POND DESIGN DETAILS", DETAIL A, TOP VIEW)

5. INSTALL THE ANTI-VORTEX COLLAR ON THE 48" RISER (SEE FIGURE 7-13 "SEDIMENT POND DESIGN DETAILS", "CLOSE UP ANTI-VORTEX DEVICE AND TRASH RACK)

6. HAVE SEDIMENT POND RECERTIFIED BY A COMPETENT REGISTERED PROFESSIONAL ENGINEER

TIME FOR ABATEMENT: MAY 8, 1984, 5:00 P.M.

FAILURE TO MEET THE EXTENDED TIME FOR ABATEMENT WILL RESULT IN THE ISSUANCE OF A FAILURE-TO-ABATE CESSATION ORDER