



DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS, AND MINING
1588 West North Temple - Salt Lake City, Utah 84116 - (801) 533-5771

56 64 16

STATE OF UTAH

Notice of Violation No. N 84-4-6-3

Violation No. 1 of 3

Nature of the Violation

FAILURE TO MINE IN ACCORDANCE WITH AN APPROVED INTERIM ^{MINE} PERMIT.
FAILURE TO PROVIDE AN ADEQUATE COMBINATION OF PRINCIPAL AND EMERGENCY
SPILLWAYS TO DISCHARGE SAFELY THE RUNOFF FROM A 25-YR, 24 HR PRECIPITATION
EVENT

Provision(s) of the Regulations, Act, or Permit Violated

UMC 771.19
UMC 817.46 (i)

Portion of the Operation to which Notice Applies

THE EMERGENCY SPILLWAY FOR THE SEDIMENT POND

Remedial Action Required (including interim steps, if any)

RECONSTRUCT THE EMERGENCY SPILLWAY TO MEET THE APPROVED DESIGN
SPECIFICATIONS

Time for Abatement (including time for interim steps, if any)

APRIL 25, 1984 5:00 A.M.



DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS, AND MINING
1588 West North Temple - Salt Lake City, Utah 84116 - (801) 533-5771

STATE OF UTAH

Notice of Violation No. N 84-4-6-3

Violation No. 2 of 3

Nature of the Violation

^{MAINTAIN}
FAILURE TO ~~THE~~ APPROVED DEWATERING DEVICE ^{D.L.} ~~(~~CONTRACT~~ ~~CONTRACT~~)~~ FOR
THE SEDIMENT POND TO ENSURE THAT THE REQUIRED THEORETICAL DETENTION
TIME CAN BE MAINTAINED AND TO PROVIDE ADEQUATE STORAGE VOLUME FOR
THE 10-YEAR, 24-HOUR PRECIP. EVENT & LESSER EVENTS.

Provision(s) of the Regulations, Act, or Permit Violated

UMC 817.46 (d)
UMC 817.46 (g)

Portion of the Operation to which Notice Applies

THE DEWATERING DEVICE FOR THE SEDIMENT POND

Remedial Action Required (including interim steps, if any)

MAINTAIN THE DEWATERING DEVICE IN ACCORDANCE WITH THE APPROVED
PLAN

Time for Abatement (including time for interim steps, if any)

APRIL 25, 1984 @ 5:00 AM.



DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS, AND MINING
1588 West North Temple - Salt Lake City, Utah 84116 - (801) 533-5771

56 64 16

STATE OF UTAH

Notice of Violation No. N 84-4-6-3

Violation No. 3 of 3

Nature of the Violation

FAILURE TO EXAMINE THE SEDIMENT POND FOR STRUCTURAL WEAKNESS, EROSION,
AND OTHER HAZARDOUS CONDITIONS AND TO PROMPTLY RECORD THE RESULTS OF
SUCH EXAMINATION IN ACCORDANCE WITH 30 C.F.R 77.216-3

Provision(s) of the Regulations, Act, or Permit Violated

UMC 817.46(e)

Portion of the Operation to which Notice Applies

THE SEDIMENT POND

Remedial Action Required (including interim steps, if any)

CONDUCT SEDIMENT POND INSPECTIONS IN ACCORDANCE WITH UMC
817.46(e) (INSPECTIONS MUST BE CONDUCTED AND RECORDED ON A WEEKLY
BASIS)

Time for Abatement (including time for interim steps, if any)

APRIL 23, 1984