

January 16, 1985

TO: Inspection Memo to Coal File
FROM: Sandy Pruitt, Mining Field Specialist *SP*
RE: Trail Mountain Mine, Diamond Shamrock Coal Co.,
ACT/015/009, File # 7, Emery County, Utah.

An inspection of the Trail Mountain Mine was conducted by Sandy Pruitt on January 16, 1985. No one was available at the mine to accompany the Inspector. Prior to this inspection, the entire mine discharge pipe to Cottonwood Creek was dismantled and stored adjacent to the substation. The original mine discharge pipe into the Sediment Pond remained in place. NOV #84-2-25-1 and the Failure to Abate CO # C85-4-1-1 were terminated effective January 11, 1985, the date the pipe was dismantled.

There was no water in the Sediment Pond although runoff was occurring in the upper part of the yard. No drainage offsite was apparent. There has been no effort to continue cleaning sediment out of the Sediment Pond.

wj
cc: Allen Childs, Diamond Shamrock
Donna Griffin, OSM
Joe Helfrich, DOGM

Statistics:

See Co-op Mine memo dated 1/16/85.

0071Q-13