

January 8, 1985

To: Coal File, Inspection and Enforcement
FROM: Sandy Pruitt, Mining Field Specialist *SP*
RE: Pattern Search, Trail Mountain Mine, Diamond Shamrock Corporation, ACT/015/009, Folder #7, Emery County Utah

During a 12 month period from September 29, 1983 to September 28, 1984 three violations were issued at the Trail Mountain Mine citing UMC 771.19. They are as follows:

1. N83-4-12-1 was issued on September 29, 1983.
2. N84-4-2-1 was issued on February 2, 1984.
3. NOV #1 of 3, N84-4-6-3 was issued on April 18, 1984.

The assessments for these violations were all finalized as of September 25, 1984. A pattern determination should be done at this time.

During the four month period from January 19, 1984 to April 18, 1984 four violations were issued under the Hydrologic Balance section. They are as follows:

1. N84-4-3-1 was issued on January 19, 1984 for failure to pass runoff through a sediment pond, UMC 817.42.
2. N84-4-4-1 was issued on January 27, 1984 for failure to inspect the sediment pond in accordance with UMC 817.46.
3. NOV #2 of 3, N84-4-6-3 was issued on April 18, 1984 for failure to maintain the sediment pond, UMC 817.46.
4. NOV #3 of 3, N84-4-6-3 was issued on April 18, 1984 for failure to inspect the sediment pond, UMC 817.46.

The assessments on these violations have been finalized.

In addition to the violations listed above three more violations under Hydrologic Balance were issued during the 12 month period up to December 31, 1984. They are as follows:

1. N84-4-10-1 was issued on July 18, 1984 for failure to meet effluent limitations, UMC 817.42.
2. NOV #1 of 2, N84-4-12-2 was issued on August 31, 1984 for failure to prevent additional contribution of sediment to streamflow and to prevent short circuiting of the sediment pond, UMC 817.42, UMC 817.46.

Page 2
ACT/015/009
January 8, 1985

3. NOV #2 of 2, N84-4-12-2 was issued on August 31, 1984 for failure to meet effluent limitations, UMC 817.42.

The assessments have not been finalized on these violations. Once they are finalized these violations should be included in support of a pattern determination for 1984 violations of Hydrologic Balance performance standards.

re
cc: Ron Daniels
Joe Helfrich
Donna Griffin, OSM