

000.1 12-28-87



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

*File*

*gn*

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Dec. 10, 1987  
9:00 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Beaver Creek Coal Company  
Business Address: P.O. Box 1378 Price, Utah 84501  
Mine Name: Trail Mountain #9 Permit Number: ACT/015/009  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official (s): Dan Guy  
State Official(s): Harold G. Sandbeck and Brent Stettler  
Partial:  Complete:  Date of Last Inspection: Oct. 14, 1987  
Weather Conditions: Cloudy and snowing  
Acreage: Permitted 1415 Disturbed 8.8 Regraded  Seeded  Bonded 8.8  
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( X )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION Dec. 10, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Dan Guy accompanied the undersigned inspector on this partial inspection. The water well next to the office has been drilled and completed. Ground conditions were wet.

2. SIGNS AND MARKERS:

A new ownership sign was posted at the main access point. The sign was current and correct. Another sign will be posted at a secondary access point as soon as it is available.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

On December 1, 1987, the operator received approval to remove and dispose of the sediment pond waste material. A contractor has been hired to dispose of the current stockpile as soon as possible.

4d. OTHER SEDIMENT CONTROL MEASURES:

Berms will be constructed around a temporary oil storage location alongside the office.

16b. ROAD DRAINAGE CONTROLS:

The storage road berms require maintenance. One area of the road requires the berm to be extended for added protection.

Copy of this Report:

Mailed to: Dan Guy, BCCC; Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Dec. 11, 1987