

0034



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

124
3/3/87

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: February 11, 1987
@ 2:00 p.m.

Permittee and/or Operators Name: Diamond Shamrock Coal Unit / Trail Mt. Coal
Business Address: P.O. Box 370 Orangeville, Utah 84537-0370
Mine Name: Trail Mountain Permit Number: ACT/015/009
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Allen Childs
State Official(s): Phil Ralphs
Partial: Yes Complete: Date of Last Inspection: 01/08/87
Weather Conditions: Partly cloudy & mild
Acreage: Permitted 778 Disturbed 8.8 Regraded Seeded Bonded 8.8
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION: 02/11/87

(Comments are Numbered to Correspond with Topics Listed Above)

4. c) Sediment Pond:

The Operator has completed sediment removal from the sediment pond. This material is temporarily being stored on site, behind and to the side of the sediment pond area. The Operator will eventually need to remove this material from the permit area as they do not have enough surface disturbed area to permanently dispose of this material. The Operator has taken samples of the material and has sent samples of to have analyzed for possible toxicities. They are presently waiting for analysis results. No problems were noted with the material at the present.

4. f) Effluent Limitations:

The Operator has recently (January) had to discharge mine water. This was the first mine water discharge in over a year. Only one discharge has occurred to date and was done in compliance with their NPDES Permit. A sample of the discharge was taken by the Operator. I reviewed the analysis results at the time of the Inspection and assured that the effluent limmits were complied with.

Copy of this Report:

Mailed to: Donna Griffin (OSM) & Allen Childs (Trail Mt)
Given to: Joe Helfrich & John Whitehead

Inspector's Signature & Number: *Philip M Ralphs*
Philip M Ralphs, #10, 2/23/87