



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

ACT 1015/009 #2  
Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

July 14, 1987

Mr. Allen Childs  
Trail Mountain Coal Company  
P. O. Box 370  
Orangeville, Utah 84537

Dear Mr. Childs:

Re: Special Conditions 5, 6 and 7 for Trail Mountain Tract 2  
Permit, Trail Mountain Coal Company, ACT/015/009, Folder #2,  
Emery County, Utah

Thank you for your response to Special Conditions 5, 6 and 7 for the Tract 2 permit. The responses adequately address requirements of Conditions 6 and 7.

The response to Condition 5 is not adequate. The necessary action is documented in the attached memo. Please respond to this deficiency no later than August 7, 1987.

Thank you for your cooperation in this matter.

Sincerely,

A handwritten signature in cursive script that reads "John J. Whitehead".

John J. Whitehead  
Permit Supervisor

djh  
Attachment  
cc: J. Fricke  
P. Grubaugh-Littig  
0800R/40

July 7, 1987

TO: John Whitehead

FROM: James R. Fricke, Reclamation Hydrologist *JRF*

RE: Special Conditions 5, 6 and 7 for Trail Mountain  
Tract 2 Permit, Trail Mountain Coal Company,  
ACT/015/009, Folder #2, Emery County, Utah

The operator's response, dated June 12, 1987, for the Trail Mountain Tract 2 Permit special conditions has been reviewed.

Condition No. 5 is not complete. Revised Figure 7-3 does not denote spring T-16 as a baseline monitor station.

Condition No. 6 is satisfied. The Forest Service field office in Ferron, Utah has notified this reviewer that the developed spring is not located in Tract 2; in fact, it is located north of Tract 2 and is no longer of any concern to the Forest Service.

The operator has sufficiently addressed Condition No. 7.

djh  
cc:  
0798R/43