

BEAVER CREEK Coal Company

Post Office Box 1378
Price, Utah 84501
Telephone 801 637-5050

Rec'd by gw 7/12
RECEIVED
MAY 13 1988



DIVISION OF
OIL, GAS & MINING

May 11, 1988

Mr. Lowell P. Braxton
Administrator
Utah Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attention: Mr. Jim Fricke

RE: Inaccessible Water Monitoring Stations, UG-1 and TM-2
Trail Mountain No.9 Mine
ACT/015/009
Emery County, Utah

Dear Mr. Braxton:

By this letter, please be advised that the 2 underground water monitoring sites at the Trail Mountain No.9 Mine are no longer accessible for sampling. The two sites, UG-1 and TM-2, were located in the South Main area of the mine. This area has recently been second mined, and is now sealed.

No data has been obtained from either point since the 4th Quarter of 1987. No further data will be submitted for these stations. If new water inflow sources are encountered in the mining, Beaver Creek Coal Company will initiate sampling and monitoring as indicated in the M.R.P.

If you need any further information, please let me know.

Respectfully,

Dan W. Guy
Manager Permitting/Compliance

cc: Johnny Coffey
Allen Childs
File

DWG/cr
IBM CATHY6