



0031

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

May 2, 1988

TO: John Whitehead, Permit Supervisor
FROM: Richard V. Smith, Geologist *RVS*
RE: Recompiled PAP Comments, Beaver Creek Coal Company, Trail Mountain #9 Mine, ACT/015/009, Folder #2, Emery County, Utah

1. Section 6.7.1, page 6-10 and Section 7.1.7, page 7-18 of the recompiled PAP neglect to incorporate the last two paragraphs of Section 7.1.6 in the Tract II PAP. The recompiled PAP must incorporate Section 7.1.6 language beginning with "Groundwater monitoring for ..." and ending with "...outflows, consumptive uses, and sump storage."
2. The last sentence in Section 6.5.1 of the recompiled PAP needs modification. The operator has drilled several boreholes within the permit area that have provided useful information.
3. Figure 7-18, entitled "Extent of Alluvium" must be submitted.
4. Maps must complement the text of the recompiled PAP by delineating a single permit area for the Trail Mountain #9 Mine.
5. Appendix 7-1 of the recompiled PAP neglects to incorporate water monitoring described in Appendix 7-1 of the Tract II PAP. This information must be included in the recompiled PAP.
6. The recompiled PAP must incorporate the commitment given in Appendix 7-1 of the Tract II PAP to develop the underground monitoring well designated TM-3. See Figure 7-9.
7. The cross reference given in the last sentence on page 2-10 in Appendix 7-10 of the recompiled PAP is no longer accurate.
8. Page 12-16 of the recompiled PAP omits the last three paragraphs in Section 12.4.3 of the Tract II PAP. This information must be incorporated into the recompiled PAP.

djh
9206R/26