



0035

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

March 31, 1988

TO: John Whitehead, Permit Supervisor
FROM: James R. Fricke, Reclamation Hydrologist *JRF*
RE: Trail Mountain Mid-Term Review, Beaver Creek Coal Company, Trail Mountain #9 Mine, ACT/015/009, Folder #2, Emery County, Utah

UMC 817.41-.46 Hydrologic Balance: General Requirements-(JRF)

The operator has provided spring and seep survey maps, however, discussion and presentation of the information derived from the 1985 survey is not presented in the reformatted MRP.

As requested previously (August 18, 1987) the Utah Power and Light Company's well, in the North Fork of Cottonwood Creek Canyon, must be located on the proper map. Additionally, discussion of adjacent water rights in Chapter 7 must reflect information from Table 7-6.

Stipulation 817.44 Hydrologic Balance: Stream Channel Diversions-(JRF)

The operator must commit to submitting a detailed channel reclamation plan for the main and side channels at the permit renewal (1989). The operator should consult with Division personnel prior to submitting the reclamation plan.

Reformatted Mine Plan Comments

- o Page 7-20, Section 7.1.7.2 must be modified to reflect the updated water monitoring plan.
- o Page 7-40, discussion on the surface water monitoring must include SW-3, this section must be revised to reflect current monitoring.

Page 2

Memo to J. Whitehead

ACT/015/009

March 31, 1988

- o Appendix 7-1 does not contain Tract II monitoring information, please provide.
- o Figure 7-2 must be updated to reflect current (Tract II) locations of water sources.
- o Figure 7-10 must be submitted.
- o Figure 7-13 must be submitted.

djh

0798R/53-54